



Manufacturing Procedures

Forming Equipment

Description	Quantity
200T Powder Compacting Press	2
100T Powder Compacting Press	1
80T Powder Compacting Press	3
60T Powder Compacting Press	2
40T Powder Compacting Press	4
20T Powder Compacting Press	9
15T Powder Compacting Press	4
8T Powder Compacting Press	2
6T Powder Compacting Press	1
3T Powder Compacting Press	1



Sintering Furnaces

Description	Max. Temp	Quantity
Belt Sintering Furnace	1150°C	4
Push Type High Temp Furnace	1450°C	1
Push Type High Temp Furnace	1300°C	1



Sizing Equipment

Description	Quantity
200T Sizing Press	1
110T Sizing Press	1
60T Sizing Press	2
45T Sizing Press	1
40T Sizing Press	2
25T Sizing Press	1
15T Sizing Press	4
8T Sizing Press	3
5T Sizing Press	2



Sintered Powder Metallurgy Processes

